Kihei02rpt-spp.doc

1. Project Name: Kihei Beach SPP

2. Date of Inspection: June 26, 2002

3. Inspection Personnel:

IHI

Name	Agency/Office	Telephone No.
a. Dan Meyers	COE	438-8875
b. Joel Hendrix	COE	438-1275
c. Ken Sivula	DP&R, Project Sup.	270-7382


4. Discussion:

The project consists of a revetment 2,697 LF. The quality and placement of the armor stones is very good. The project begins at Sta. 0+70 (north side) and ends at Sta. 26+97 (south side). The project was modified in 1999 by DPW, where a storm drain outlfall was installed thru the revetment at Sta. 23+75. This modification was accomplished w/o DP&R or COE review. We discussed the need to notify the COE prior to any future modifications prior to commencement of work. The major concerns/deficiencies are as follows:



a. Sta. 0+05 to Sta. 0+30, Remove the vegetation from crest and sideslope.





b. Sta. 3+00, 1st Walkway, photo for reference.



c. Sta. 3+48, Monitor the armor stone resting adjacent the toe.





d. Sta. 3+76, Monitor the area adjacent to cracked armor stone for settling.



e. Sta. 8+41, Monitor the dislodged armor stone adjacent the toe.





f. Sta. 8+73, 2nd Walkway, photo for reference.



g. Sta. 9+57, Add fill material to the eroded area.




h. Sta. 9+89, Monitor the depressed area on sideslope.



i. Sta. 12+92, Monitor the depressed area on sideslope.





j. Sta. 13+29, Remove the tree from tie-back sideslope.



k. Sta. 14+05, Remove the vegetation from tie-back sideslope.



1. Sta. 16+96, Remove the vegetation from crest.



m. Sta. 17+89, Remove the concrete pad and vegetation.

HAH



n. Sta. 21+17, Remove the tree from the crest.




o. Sta. 23+11, 3rd Walkway, repair the concrete invert.






p. Sta. 23+75, Monitor the sideslope settling on the southside of the culvert.



q. Sta. 24+00, Overview, photo for reference.

IKI



r. Sta. 25+14, Reset the missing armor stone and monitor area for settling.



s. Sta. 25+87, Remove the vegetation from crest.

Kihei02rpt-spp.doc



t. Sta. 26+06, Reset the missing armor stone.



u. Sta. 26+97, End of project (south), photo for reference.

CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT FOR HURRICANE & SHORE PROTECTION PROJECTS Honolulu Engineer District CEPOH-EC-T

Kihei02rpt-spp.doc

5. Conclusion:


The overall rating of the project is Excellent. In accordance with ER 500-1-1, (dtd 30 September 2001), and based on this CEI, the Project is rated **SATISIFACTORY**, Project Condition Code is **ACCEPTABLE** and the project is considered **ACTIVE** in the Rehabilitation and Inspection Program. Discrepancies were noted and suggestions were made to the DPW representative.

	Signed:
	Dan Meyers, CEPOH-EC-T
	Signed:
	James Pennaz, P.E., Ch, CEPOH-EC-T
closure(s)	

Enclosure(s)
Site Plan

IIWII

Kihei02rpt-spp.doc



CONTINUING ELIGIBILITY INSPECTION (CEI) REPORT FOR HURRICANE & SHORE PROTECTION PROJECTS Honolulu Engineer District

Honolulu Engineer District CEPOH-EC-T

Kihei02rpt-spp.doc

KIHEI BEACH, MAUI, HAWAII

CONDITION OF IMPROVEMENT 30 SEPTEMBER 1989

PREVIOUS PROJECTS: None.

EXISTING PROJECT: Authorized under Section 103 of the River and Harbor Act of 1962, as amended. Provides for a protective stone revetment, 2,610 feet long and crest elevation 8.0 feet MLLW; and a recreational beach berm approximately 20 feet wide, and 2,610 feet long. The seaward slope of the revetment is armored with 1,000-pound stone placed on a slope of 1 vertical to 3 horizontal. The revetment toe is placed on the underlying coral strata excavated to a depth of -4.5 feet below MLLW.

PROGRESS OF WORK

Completed and Under Maintenance: The project was completed in June 1971, except beach access walkway which was completed in December 1971.

Work Remaining: None.

COST OF CONSTRUCTION:

		New Work
Completed	Worke.	

United States Funds \$154,313

Contributed Funds

Required 154,313 Other 44,667

Total Costs \$353,293

RANGE OF TIDES: The tidal range between mean lower low water and mean higher high water is 2.3 feet.